anitized Copy Approved for	or Release 2011/08/22 :	CIA-RDP90B00224R00030035	0004-0 ks C
•	Info to	- AES MAL	MR
VIA AIR (Specify Air or Sea Pouch)	•	dispatch no	25X^
	POP SE C	CRET	
ro:		DATE 4 March 199	5 8 25X
PROM:			25X′
	nander's Mission Rep	ort	
SUBJECT { SPECIFIC :	Mission 601	L	25X ²
ATTACHMENT: As Stated	in 1958. T.S. 16066	4, Copy 1 of 2 copies.	25X
			№ 25X1
	e r		
		Reclassify SECRET when separated from top secret enclosure.	

TOP SECRET

94

TOP	SECRET	T
-----	--------	---

		Ţ	OF SEC.	RET		
TO:					4 March 1958	25)
FROM:						25)
 Subject	GENERAL:	Commander's	Mission Repo	rt		
	SPECIFIC					25)
it is feature it is feature it is feature it is feature it is not on the seature it is feature it is soon. Have	t were major fed and priselt that lifel. Fault by turbulen considered eouts under ere during viest encours over the state of the state	ttle was lost y face heat c ce caused fla as a malfunct similar condi the past few in tered thus fa Sea of Japan a ever, a serior enetration mis haracteristics eather permits	operated such as the missiaused the tal meout on with ion of the enitions have had been us factor and ssions. A test of the engine.	because pilot cessfully in ion apparentl ce-off to be adrawal route agine install been encounte extreme turb ject, has fo restricted to should be a est flight will ne installed	delayed 4 minutes This flameout ed in aircraft 378 red in other air- ulence, possibly rtunately been the lower lati- consideration in ll be made to in aircraft 378	
n this ondition ircraft having hake the	case that in and with performed gra 100% mie aircraft	t was unavoid the exception satisfactoril ssion would b down after se	not desirable iable. The an of a malfun believe enhanced beveral local	e, however, in ircraft was increaft was increased as a general year allowing the flights.	it is realized in reasonably good to heat system the ill rule our chances are ground crew to	
., acca	elieve the al loss of dditional e	TTOTOME DIOL	ssion 6011 s ted against	hould be chec the benefits	ked closely and obtained by use	
Supp	port in all	areas was ou	tstanding.			
						25>
						4
	`					
		TO	STER!	TT Observed	T.S. 16066	<i>I</i> .
		1,00				copies25

Sanitized Copy Approved for Release 2011/08/22 : CIA-RDP90B00224R000300350004-0